TOP 10

Root Causes of Inadequate LOCKOUT TAG OUT in the Food Manufacturing Industry

BY THE INDUSTRY, FOR THE INDUSTRY

A food manufacturing industry workshop of workers, supervisors, and employers, facilitated by WSPS, identified the top 10 primary causes of inadequate lockout tag out.

1. Leadership commitment
2. Lack of procedures (program)
3. Inadequate training
4. Low risk perception/ acceptance of risk
5. Rushing
6. Procedures not followed
7. Inadequate monitoring and enforcement
   Inadequate LOTO devices
8. Lockout point not accessible
9. Inadequate procedure
10. Inadequate metrics (production rate, downtime, financial growth)

Connect with us to learn more about the industry-identified risks, root causes, and recommended solutions that address inadequate lockout tag out in the workplace.

Learn more at Top Risks in Food Manufacturing & Root Cause Analysis | WSPS

For more information contact Workplace Safety & Prevention Services
wsps.ca **1 877 494 WSPS (9777)**
CONNECT WITH US

Workplace Safety & Prevention Services®

810-BOS-01-IMOT | SEPT 2023